

Arbortech Number	Carat Number	Drawing reference	Contents	QTY
MIN.FG.FAST900	0398 04AMG9001	10	Screw, M4 x 20 Socket Head	2
		11	M4 X 25MM Socket Cap Head	2
		30	Screw, 4g x 1/2 self tapping /Phillips pan head	4
		27	Screw, 6G 1/2 S/Tap Screw (BLACK ZINC)	2
		9	Screw, 5 x 18 mm BHSS Button Head	1
		28	M5 x 17mm OD X 2mm washer	1
		34	M4 Plain Washer ZN	6
MIN.FG.PULLEYKIT900	0398 04AMG9002	20	Ribbed Driving Pulley M14	1
		19	Ribbed Driven Pulley	1
ACC.FG.HANDLE600	0398 04AMG9003	See Diagram	Grinder Handle	1
MIN.FG.ARMKIT900	0398 04AMG9004	5	Arm, Mini Carver	1
		23	Locking Bar	1
		4	Belt adj-t bush	1
		7	Guard beltcover	1
		24	Locking button	1
		6	Duct cap	1
		8	Duct cover	1
		13	Spindle lock Cover	1
		12	Bearing seat	1
22	Leaf Spring	1		
ACC.FG.BRUSH900.00	0398 04AMG9005	See Diagram	Brush set for AT3107 / 230Volt Grinder	1
ACC.FG.MOTOR900.60	0398 04AMG9006	See Diagram	Motor 230V/1050W AT3107 EUR 115-VAR Speed	1
MIN.FG.BELT900	0398 04AMG9007	15	Belt, Ribbed PJ300.2 Ribs	1
MIN.FG.900-05	0398 04AMG9007	26	Bearing, ball for Mini grinder & C/Sander	1
		1	Mini Carver Shaft 900	1
MIN.FG.SPACER600	0398 04AMG9009	25	Pulley Step Spacer for Mini Carver	1

